



TECHNICAL SERVICE

Service Advisory #4

Date: March 2017

SKYJACK TECHNICAL SERVICE 3451 SWENSON AVE. ST. CHARLES, IL. 60174
TOLL FREE: **800-275-9522** PHONE: 630-262-0005 FAX: 630-262-0006

CHAIN/ROLLER INSPECTION AND MAST LUBRICATION APPLIES TO: SJ12, SJ16 Vertical Masts

A failure to inspect and perform required maintenance on the lifting mechanism of the mentioned product may result in the mast assembly not operating properly and potentially causing sudden, unexpected movements. To prevent malfunction, perform the prescribed maintenance as outlined in the current Service manual.

As outlined in the applicable Skyjack Service manuals and various applicable regulations, this inspection and maintenance must be completed as part of the required frequent/periodic, 6-month and annual inspections.

Refer to the most current Service Manual applicable to your unit's serial number from Skyjack's website (www.skyjack.com). This service advisory is also available on our website at: www.skyjack.com/service-advisories.

You must: Perform the following inspections and maintenance by following the instructions listed in Section 1 of the applicable Service Manual and by referring to the referenced procedures in Section 5:

Mast assembly inspection and lubrication
Mast chains inspection
Rollers inspection
Wear pad inspection

If the recommended inspections and maintenance have not been performed within the required intervals by a qualified person, Skyjack recommends those units be removed from service **immediately** and have the required inspections and maintenance performed before placing the unit back into service.

Any units identified with damage must be **immediately removed from service** and repaired by a qualified technician.

If you require further information regarding this supplement, please contact Skyjack Service at 1-800-275-9522 or 44 1691 676 235. You may e-mail questions to service@skyjack.com.

Ownership of Machines:

Skyjack requires that you promptly notify us of a new owner's contact information if you have sold or transferred any machine. Please forward this service advisory to the new machine owner.